


Overview Map showing eCityRisk data coverage for affected buildings in Christchurch CBD following the 2011 Canterbury Earthquake



NZ Christchurch CBD Footprints

Damage Description

- Collapsed
- Very heavy damage or collapsed
- Very heavy
- Moderate
- Up to moderate
- Negligible to slight
- Slight



ecityrisk

eCityRisk USA *400 Oceangate, Suite 1050, Long Beach, California, 90802, USA) +1 562 628 1675
eCityRisk UK *Communications House, 63 Woodfield Lane, Ashted, Surrey, KT21 2BT, UK) +44 2081 239864

www.ecityrisk.com